

GPS position	Type	Description	Photo ID
1 SJ2000060095	Shaft vent?	Steel pipe 14"H x 5"DIA, contains 1" rubber hose.	SJ2000060095d
2 SJ1998460071	cave ? " GOGS IN "	15"W x 30"H, choked with leaves	SJ1998460071a SJ1998460071b
5 SJ1998160061	cave ? - 11 -	24"W x 24"H. seems to go back	SJ1998160061
6 SJ1995159908	cave	36"W x 24"H. Part of surface mine gully?	SJ1995159908a
7 SJ1992960152	vertical shaft	6' DIA, stone lined-fenced.	SJ1992960152a SJ1992960152b
8 SJ1987160111	vertical shaft	3' DIA, stone lined-fenced.	SJ1987160111
9 SJ2008460227	Shaft vent?	Steel pipe 14"H x 5"DIA, contains 1" rubber hose.	SJ2008460227b
10 SJ2002059882	"DGG" - MINING AREAS Caves	Two openings, ~45deg slope.	SJ2002059882d
11 SJ2007359962	vertical	Two rectangular openings, filled with leaves	SJ2007359962
12 SJ2007060767	?	Depression under leaf cover - look at again.	
13 SJ1991160814	?	Exposed face ~2ft x 2ft	SJ1991160814
14 SJ1990660814	"Cave" - MINING TUNNEL	Shaft approx 4' x 4', ~45deg slope horizontal wooden beam.	SJ1990660814a SJ1990660814b &c
15 SJ1974060144	"adit/drainage?" "GET ACCESS TO WRENCHES?"	Near Maenlas spoil. Gully leads to opening? Blocked with tree stumps.	SJ1974060144b SJ1974060144a
16 SJ1965659941	vertical shaft "Like scouse pot"	Irregular ~5' x 4'. Not faced with masonry - seems to be natural rock. Partial fence.	SJ1965659941
17 SJ1970859863	vertical shaft	3' dia. stone lined-fenced	SJ1970859863
18 SJ1984960130	vertical shaft	3' dia. stone lined-fenced	SJ1984960130
19 SJ2006759931	vertical shaft	~12" x 12" small opening - used by animals?	SJ2006759931
20 SJ1973459854	vertical shaft	3' dia. East of 'Scouse Pot' on your site?	

19292-59632  
19328-59682  
2006659858

SHAFT RV Ruins  
CROG? 6' ARMS  
CROSS (20' WEST)  
OUT CROG 2' x 2'

31